



Stop the work if you are sick. Prevent the pressure pulsing. Don't apply voltage. Use a converter while measuring high temperature. Don't stick your arm in the device or in the ventilator box. Don't touch with cold hands. Don't weld or cut vessels.



Users should read it carefully. Put on a safety helmet. Don't let the rheum get in your eyes. Wash your eyes and turn to the doctor. Use a gas mask. Don't break the ice on sight glasses.



Don't store containers with flue under the atmospheric temperature. As soon as you find a strong smell and cough, warn the employees and leave the building immediately. Don't use the damaged containers. Keep the floor clean, wipe the spilled cold.



Use nitrogen. Don't inhale the vapor from leak finder. Don't turn on when having sucking and pumping flue. Don't enter the room. Don't blow the evaporator with vapor. Don't store flue containers close to one another. Don't stand beside spinning nasopharynxes.



Wear gloves while working with nasopharyngeal knots. Don't wear a tie when working in close proximity. Use immunity boosting means. Apply safe work methods. Crack open the faucet. Power down the regulating torx. Do not dismantle the nasopharynx or other knots when the system is under pressure.